Approving National Aviation   2.					3. Fc	Form Tracking Number.		
Authority/Country: AUTHORIZED RELEASE CERTIFICATE					103	102176		
FA	FAA/UNITED STATES FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG							
TACT CHIM CLOSES, AMENOCATION LEGAL TACE								
4. Organization Name and Address. Freedom Aero Service Inc. 3200 Howard Street					5 10/6	5 Mark Order Contract or		
McClellan, CA 95652				5. Work Order, Contract or Invoice Number:				
USA				W23594				
Ph: 916 434-5194, Fax: 916 431-5637			37		VV23334			
FAA Approval Holder: 25FR283B								
6. Item	7. Description:	8. Part Number	er:	9. Quantity:	10. Seria	al Number:	11. Status/Work:	
1	Circuit Card	350A61-1750-	00	1	21382-1		REPAIRED	
12. REN	MARKS							
DED	NPED in accordance wit	n Repair spec FRS-28 Rev Ori	a 7/15/15					
			g //13/13					
Full details of work held on work order No: W23594								
Certifies work specified in Blocks 11/12 was carried out in accordance with EASA part 145, and with respect to that work, the article is considered ready								
for release to service under EASA Part 145 Approval Number EASA 145-6177								
13a. Certifies the items identified above were manufactured in conformity to:				14a X 14 CFR 43.9 Return to Service X Other regulation specified in Block 12				
Approved design data and are in a condition for safe operation.				Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and with respect to that work, the items are approved for return to				
Non-approved design data specified in Block 13								
Tron approved design data specified in block 15				rvice.	·			
						T.:		
13b. At	3b. Authorized Signature: 13c. Approval Authorization No:		0: 14b	. Authorized Signature:	1.	14c. Approval/Certificate No:		
			1	11111111 1111	1/1	25FR283B		
13d. Na	ame (Typed or Printed):	13e. Date (dd/mmm/yyyy):	14d.	Name (Typed or Printed):		14e. Date (dd/mmn	n/yyyy):	
				/	NCON	26/Mar/2021		
				MICHAEL JOHNSON		ZOMIGITZOZ I		
			User/Installer Respo	onsibilities				
It is imp	ortant to understand that the e	xistence of this document alone does	not automatically constitute	authority to install the engine	e/propeller/articl	le.		
Mhere t	he user/installer performs work	in accordance with the national regul	ations of an ainworthinges	authority different than the air	worthiness auth	pority of the country en	acified in Block 1 it is	
		s that his/her airworthiness authority a						
Ctatama	nt in Placks 12s and 14s ds =	ot constitute installation cortification.	a all agges piroroft mainten	anaa raaarda muut aastsis se	installation ser	tification issued in an	pordanae with the	
		ot constitute installation certification. In er before the aircraft may be flown.	i ali cases aircrait mainten	ance records must contain an	i installation cer	uncation issued in acc	cordance with the	
		,						

FAA Form 8130-3 (02-14) NSN:0052-00-012-9005

## Work Order #: W23594



## WorkOrder

Freedom Aero Service Inc. Certified Repair Station # 25FR283B EASA145.6177

3200 Howard St McClellan, CA 95652 PH: 916-434-5194 FX: 916-434-5637 Work Type: Repair Priority: Routine

Cust PO: R2021-37D

Warranty: No Page: 1 of 1

Customer: RotorLink Technical Services

PN: 350A61-1750-00

Description: Circuit Card

TSN:

Qty: 1

Discrepancy

TSO: TSR:

Specification: Repair spec FRS-28 Rev Orig 7/15/15

Hidden Damage: N/A

Searched for applicable AD's: None found

Serial Number(s): 21382-1

Task: Preliminary Inspection

Start:



Stop or Complete:



Preliminary Inspection

Action: 2 DSQ sockets have bent pins, require replacement(S3, S6). Electronics pass testing. Several faulty solder joints require repair. 4 screws are missing and require replacement. MTA Sockets F,G,H,I,J,K,M,N,Q,R are corroded and require replacement.

Inspected by: Mike Johnson 3/18/2021 12:38:18 PM

Task: Repair/In Process Insp

Start:



213498S

Stop or Complete:



Repair/In Process Insp

Action: Repaired, Replaced 2 DSQ sockets, Replaced MTA sockets, Replaced 4 screws, Re-soldered all faulty and questionable solder joints. Repaired 3 corroded traces. Cleaned and applied new conformal coating. All checks pass in accordance with FRS-28

Inspected by: Mike Johnson 3/26/2021 2:40:44 PM

Task: Final Inspection



Final Inspection

Action: Inspected.

Stop or Complete:



213499C

Inspected by: Mike Johnson 3/26/2021 2:40:55 PM

Maintenance Release: The appliance identified above was repaired and/or inspected in accordance with current Regulations of the Federal Aviation Administration and, with respect to the work performed, is airworthy and approved for return to service.

MICHAEL JOHNSON

Name (Typed or Printed)

**Authorized Signature** 

Inspectors Stamp