


1. Approving Civil Aviation Authority/Country Transport Canada		2. AUTHORIZED RELEASE CERTIFICATE FORM ONE			3. Form Tracking No. 34-14574	
4. Organization Name and Address Vector Aerospace – Helicopter Services North America 4551 Agar Drive Richmond, B.C. V7B 1A4				5. Work Order/Contract/Invoice 34-14906		
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial/Batch No.	11. Status/work	
1	Governor	2524692-11 23065125	1	BR36252	Repaired	
12. Remarks Repaired and tested IAW Honeywell OHM Form 15-1001A, dated Sept.4/01, up to and including T/R 73-12. CEB 73-3139 Rev.1 and GT 73-367 complied with. TSN : N/K TSO : 1154.5 -----Last Line-----						
Work performed in accordance with <input checked="" type="checkbox"/> FAR 43 <input checked="" type="checkbox"/> E.A.S.A. 145.7003						
13a. Certifies that the items identified above were manufactured in conformity to: <input type="checkbox"/> approved design data and are in condition for safe operation. <input type="checkbox"/> non-approved design data specified in block 12.			14a. <input checked="" type="checkbox"/> CAR 571.10 Maintenance Release. <input checked="" type="checkbox"/> Other regulation specified in block 12. Certifies that, unless otherwise specified in block 12, the work identified in block 11 and described in block 12 has been performed in compliance with the <i>Canadian Aviation Regulations</i> .			
13b. Signature		13c. Approved Organization Number	14b. Signature 		14c. Approved Organization Number AMO 231-91	
13d. Name		13e. Date (dd/mmm/yyyy)	14d. Name Michael Goodman		14e. Date (dd/mmm/yyyy) 24-Sep-2014	

(Previously form 24-0078)

Important: See notes

INSTALLER RESPONSIBILITIES

This certificate does not constitute authority to install.


Installers working in accordance with the national regulations of a country other than that specified in block 1 must ensure that their regulations recognize certifications from the country specified.

Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.

Vector Aerospace

4551 Agar Drive, Richmond, BC Canada V7B 1A4

CUSTOMER'S PROPERTY IDENTIFICATION TAG

Description: GOVERNOR Engine Model: C30P
Item P/N: 23063625 Item S/N: BR 36852 Quantity: 1
Remove from: Engine [] Module [] or HMU/FCU [] S/N: CAE-895097
Removal Reason: Sudden Stoppage
Item Total Time Since New: UNK Item Total Cycles Since New: N/A
Item Total Time Since Overhaul: 1154.5 Item Total Cycles Since Overhaul: N/A
Customer Name: RoboLink Technical Services
Customer PO: 10435 W/O Number: 34-14574
Inspector: Am  Date: AUG 05 2015
Comments: Return as IS.

NOTICE

The item identified on the reverse side of this tag was removed due to reasons such as service bulletin incorporation, attrition, conversion from one model to another model, insufficient time and/or cycles remaining on life limited items or other customer requests. The customer must perform further inspection of the item before use to determine serviceability. Pertinent details of work performed are on file at this facility under work order number listed on the reverse side of this tag.

Service Accessory Record



Rolls-Royce

Nomenclature GOVERNOR

Part I
Page No. 1

Component Serial Number BR36252

Engine Model 250-C30P

Installed					Removed			
Date	Engine S/N	A/C S/N	Accessory Time		Date	Accessory Time		Reason
		Reg. No.	Since OH	Total		Since OH	Total	
5-15-08	CAE-893097	51143	New	0.0	SEP 05 2014	1154.5	UNK	LEB-73-3139.
		N 850C						
			1154.5	UNK				

Inspection - Maintenance - Overhaul - Transfer AD/CEB compliance record accessory



Rolls-Royce

Nomenclature GOVERNOR

Part II
Page No. 1

Component Serial Number BR36252

Engine Model 250-

Note 1: Record AD & CEB compliance and transfer information in "Remarks" section.

Note 2: This card must accompany accessory at removal.

Date	P/N	Accessory Time		Remarks	Signature and Certificate No.
		Since OH	Total		
		New	0.0	Shipped from Rolls-Royce to:	Rolls Royce
FEB-19 2008	23065125	00.00	UNK	O/A REF. HONEYWELL O/A MAN 73-20-09 RQW#2 REF WO#039355	Serviced By Ph: 620-331-7716 FAA Repair Station VKUR823L Independence, Kansas 67301 www.kansasaviation.com
2-17-09	23065125	613.4	N/A	C/W ASB 2066-08-151 REVA I/A/W CEB-73-3126 N/A by P/W.	AP2779747 EGTA 597j
Sept. 24/14	23065125	1154.5	UNK	Repaired and tested IAW Honeywell OHM Form 15-1001A on vector w/o 34-14906 CEB 73-3139 Rev.1 and GT 73-637 complied with	