1. Approving national aviation authority/country	2.	3. Form tracking No.
Transport Canada	**AUTHORIZED RELEASE CERTIFICATE FORM ONE**	1215161495

4. Organization name and address	5. Work order/contract/invoice
Canadian Aero Accessories Ltd. **170 George Craig Blvd. N.E. Calgary, AB, Canada T2E 7H2**	161495

6. Item	7. Description	8. Part No.	9. Qty.	10. Serial/batch No.	11. Status/work
1	HYDRAULIC PUMP	66005-01 (212-076-011-101)	1	K0157	OVERHAULED

12. Remarks

Overhaul and acceptance test carried out.

13a. Certifies that the items identified above were manufactured in conformity to:

☐ **Approved design data and are in condition for safe operation.**

☐ **Non approved design data specified in block 13.**

14a.

☑ **CAR 571.10 Maintenance release.**

☐ **Other regulations specified in block 12.**

Certifies that, except where otherwise specified in block 12, the work identified in block 11 and described in block 12 was performed in accordance with Canadian Aviation Regulations.

13b. Signature	13c. Approved Organization Number	14b. Signature	14c. Approved Organization Number
N/A	N/A	Dennis Fell (CAA 6 LTD.)	AMO 30-87
13d. Name	**13e. Date (dd/mmm/yyyy)**	**14d. Name**	**14e. Date(dd/mmm/yyyy)**
N/A	N/A	Dennis Fell	23/DEC/2015

This certificate does not constitute authority to install.

Installers working in accordance with the national regulations of a country other than that specified in block 1 must ensure that their regulations recognize certifications from the country specified.

Statements in block 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.

CANADIAN AERO ACCESSORIES LTD.

PHONE: (403) 250 9077 FAX: (403) 250 6841 www.canadianaero.com
TCCA: **AMO 30-87** EASA PART-145 Approval Certificate Reference Number **EASA.145.7019**

INSPECTION / TEARDOWN REPORT

Customer Repair Order: **10592B**	Removed From: **JA9518**	CAA Work Order: **161495**

Description: **HYDRAULIC PUMP** Part Number: **66005-01** Serial Number: **K0157**	Other Identification Data: **212-076-011-101** Time In Service: **N/A**

1. WORK REQUESTED ↓

Functional Test ☐ Inspection ☐ Repair ☐ Overhaul ☒ Brush Change ☐ Bearing Change ☐ Modification ☐

Hydrostatic Test ☐ Warranty ☐ Other:

2. REASON FOR REMOVAL ↓

Scheduled / Time Expired ☐ No Snag Reported ☐ Unscheduled / Snag ☒ *INOP*

3. PRETEST ↓

No ☒ Yes ☐

4. FINDINGS ↓

EXTERNAL CONDITION: NORMAL
INTERNAL CONDITION: SEALS AND O-RINGS WORN. ALL OTHER PARTS OK.PERFORM ROUTINE OVERHAUL

5. WORK (TO BE) ACCOMPLISHED ↓

Disassembly ☒	Wiring Repairs ☐	Other Work:
Partial Disassembly ☐	Dynamic Balancing ☐	
Cleaning ☒	Re-Lubrication ☐	
Paint stripping ☐	Re-Soldering ☐	
Inspection ☒	Parts Replacement ☒	
NDT ☐	Recharge / Re-Fill ☐	
Hydro-Static Test ☐	Reassembly ☒	
Commutator / Slip-Rings Restoration ☐	Run-in ☐	
Contacts Restoration ☐	Acceptance Test ☒	
Seals Resurfacing ☐	Paint ☐	

6. NOTES ↓

Technician: *JG*

Report Prepared By: *KATHY JOHNSON*