

LOG CARD

Sezione 2

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Chapter n°65.....
Part n°

COMPONENT DATA				INSTALLATION				REMOVAL			
DESCRIPTION (28)	P/N (29)	S/N (30)	RETIREMENT LIFE (31)	ASSY TOTAL TIME (32)	COMP. TOTAL TIME (33)	COMP. TIME SINCE OH (34)	STAMP AND SIGNATURE (35)	ASSY TOTAL TIME (36)	COMP. TOTAL TIME (37)	COMP. TIME SINCE OH (38)	STAMP AND SIGNATURE (39)
MAIN ROTOR BLADE BOLT	109-8101-47-109	V365		00:00	00:00	NEW	A15 010				
MAIN ROTOR BLADE BOLT	109-8101-47-109	V366		00:00	00:00	NEW	A15 010				
MAIN ROTOR BLADE BOLT	109-8101-47-109	V367		00:00	00:00	NEW	A15 010				
MAIN ROTOR LAG DAMPER	109-0112-05-107	0076		828.5	1633.1	00:00	2-12-15	1464.9	2269.5	636.4	7/7/16
Damper Bracket Assy	109-0111-07-117	2062		1628.9	0.0	NEW	11-8-16	WIK	WIK	NEW	7/7/16
Damper Bracket Assy	109-0111-07-117	2070		1628.9	0.0	NEW	11-8-16	2429.8	500.4	NEW	10/25/15
M/R Dub Assy.	109-0111-03-113	R840	2429.8 591.9	927.4 1591.6	NEW	11-8-16					
Bandar Bracket Assy	109-0111-07-117	V329	3229	3229.0	WIK	11-8-16	4088.5	799.5	NEW	10-3-22	
Bandar Bracket Assy	109-0111-07-117	1589		3229.0	WIK	11-8-16	4088.5	799.5	NEW	10-3-22	
Dampers Bracket Assy	109-0111-07-117	A1319		3229.0	WIK	11-8-16	4088.5	799.5	NEW	10-3-22	
5-1589-0111-07-117	109-0111-11-105	RJ225		3229.0	0.0	NEW	11-8-16				
5-1589-0111-07-117	109-0111-04-101	N10120		3229.0	0.0	NEW	11-8-16				

Rev. 3

AQ 12-04

LOG CARD

Sezione 2

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Chapter n°65.....
Part n°

COMPONENT DATA				INSTALLATION				REMOVAL			
DESCRIPTION (28)	P/N (29)	S/N (30)	RETIREMENT LIFE (31)	ASSY TOTAL TIME (32)	COMP. TOTAL TIME (33)	COMP. TIME SINCE OH (34)	STAMP AND SIGNATURE (35)	ASSY TOTAL TIME (36)	COMP. TOTAL TIME (37)	COMP. TIME SINCE OH (38)	STAMP AND SIGNATURE (39)
DROP STOP PLATE	109-0111-17-101	V123		00:00	00:00	NEW	A15 010	2429.8	2429.8	NEW	10/01/8
DROP STOP PLATE	109-0111-17-101	V124		00:00	00:00	NEW	A15 010	2429.8	2429.8	NEW	10/01/8
DROP STOP PLATE	109-0111-17-101	V145		00:00	00:00	NEW	A15 010	2429.8	2429.8	NEW	10/01/8
LOCKING DAMPER PIN	109-0111-30-101	OM621		00:00	00:00	NEW	A15 010				
LOCKING DAMPER PIN	109-0111-30-101	OM622		00:00	00:00	NEW	A15 010				
LOCKING DAMPER PIN	109-0111-30-101	OM623		00:00	00:00	NEW	A15 010				
LOCKING DAMPER PIN	109-0111-30-101	OM624		00:00	00:00	NEW	A15 010	2429.8	2429.8	NEW	10/01/8
FLAPPING LIMITER SUPPORT ASSY	109-0111-33-101	V99		00:00	00:00	NEW	A15 010				
FLAPPING LIMITER SUPPORT ASSY	109-0111-33-101	V100		00:00	00:00	NEW	A15 010				
FLAPPING LIMITER SUPPORT ASSY	109-0111-33-101	V101		00:00	00:00	NEW	A15 010				
FLAPPING LIMITER SUPPORT ASSY	109-0111-33-101	V102		00:00	00:00	NEW	A15 010				
UPPER FLAPPING LIMITER	109-0111-34-101	V91		00:00	00:00	NEW	A15 010				

Rev. 3

AQ 12-04

LOG CARD

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Sezione 2

Chapter n°65.....
Part n°

COMPONENT DATA				INSTALLATION				REMOVAL			
DESCRIPTION (28)	P/N (29)	S/N (30)	RETIREMENT LIFE (31)	ASSY TOTAL TIME (32)	COMP. TOTAL TIME (33)	COMP. TIME SINCE OH (34)	STAMP AND SIGNATURE (35)	ASSY TOTAL TIME (36)	COMP. TOTAL TIME (37)	COMP. TIME SINCE OH (38)	STAMP AND SIGNATURE (39)
UPPER FLAPPING LIMITER	109-0111-34-101	V90		00:00	00:00	NEW	A15 010				
UPPER FLAPPING LIMITER	109-0111-34-101	V92		00:00	00:00	NEW	A15 010				
UPPER FLAPPING LIMITER	109-0111-34-101	V93		00:00	00:00	NEW	A15 010				
FLAPPING LIMITER PIN	109-0111-36-101	V201		00:00	00:00	NEW	A15 010				
FLAPPING LIMITER PIN	109-0111-36-101	V202		00:00	00:00	NEW	A15 010				
FLAPPING LIMITER PIN	109-0111-36-101	V203		00:00	00:00	NEW	A15 010				
FLAPPING LIMITER PIN	109-0111-36-101	V204		00:00	00:00	NEW	A15 010				
MAIN ROTOR GRIP ASSY	109-0112-03-101	V315		00:00	00:00	NEW	A15 010	2429,8	2429,8	NEW	10/25/18
MAIN ROTOR GRIP ASSY	109-0112-03-101	V314		00:00	00:00	NEW	A15 010	2429,8	2429,8	NEW	10/25/18
MAIN ROTOR GRIP ASSY	109-0112-03-101	V313		00:00	00:00	NEW	A15 010	2429,8	2429,8	NEW	10/25/18
MAIN ROTOR GRIP ASSY	109-0112-03-101	V317		00:00	00:00	NEW	A15 010	2429,8	2429,8	NEW	10/25/18
PITCH CONTROL LEVER ASSY	109-0112-04-101	V196		00:00	00:00	NEW	A15 010				

Rev. 3

AQ 12-04

LOG CARD

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Sezione 2

Chapter n°65.....
Part n°

COMPONENT DATA				INSTALLATION				REMOVAL			
DESCRIPTION (28)	P/N (29)	S/N (30)	RETIREMENT LIFE (31)	ASSY TOTAL TIME (32)	COMP. TOTAL TIME (33)	COMP. TIME SINCE OH (34)	STAMP AND SIGNATURE (35)	ASSY TOTAL TIME (36)	COMP. TOTAL TIME (37)	COMP. TIME SINCE OH (38)	STAMP AND SIGNATURE (39)
PITCH CONTROL LEVER ASSY	109-0112-04-101	V197		00:00	00:00	NEW	A15 010				
PITCH CONTROL LEVER ASSY	109-0112-04-101	V198		00:00	00:00	NEW	A15 010	3885,5	3885,5	NEW	L.S.N.
PITCH CONTROL LEVER ASSY	109-0112-04-101	V201		00:00	00:00	NEW	A15 010				
MAIN ROTOR LAG DAMPER	109-0112-05-107	MCR2386		00:00	00:00	NEW	A15 010	1156,0	1156,0	NEW	11/10/15
MAIN ROTOR LAG DAMPER	109-0112-05-107	MCR2384		00:00	00:00	NEW	A15 010	1156,0	1156,0	NEW	11/10/15
MAIN ROTOR LAG DAMPER	109-0112-05-107	MCR2385		00:00	00:00	NEW	A15 010	1156,0	1156,0	NEW	11/10/15
MAIN ROTOR LAG DAMPER	109-0112-05-107	MCR2383		00:00	00:00	NEW	A15 010	828,5	828,5	NEW	11/10/15
MAIN ROTOR BLADE BOLT	109-8101-47-109	V360		00:00	00:00	NEW	A15 010				
MAIN ROTOR BLADE BOLT	109-8101-47-109	V361		00:00	00:00	NEW	A15 010				
MAIN ROTOR BLADE BOLT	109-8101-47-109	V362		00:00	00:00	NEW	A15 010				
MAIN ROTOR BLADE BOLT	109-8101-47-109	V363		00:00	00:00	NEW	A15 010				
MAIN ROTOR BLADE BOLT	109-8101-47-109	V364		00:00	00:00	NEW	A15 010				

Rev. 3

AQ 12-04

X
A
A
A

29-14

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Chapter n°65.....
 Part n°


COMPONENT DATA				INSTALLATION				REMOVAL			
DESCRIPTION (28)	PN (29)	S/N (30)	RETIREMENT LIFE (31)	ASSY TOTAL TIME (32)	COMP. TOTAL TIME (33)	COMP. TIME SINCE OH (34)	STAMP AND SIGNATURE (35)	ASSY TOTAL TIME (36)	COMP. TOTAL TIME (37)	COMP. TIME SINCE OH (38)	STAMP AND SIGNATURE (39)
MAIN ROTOR HUB ASSY	109-0111-03-113	V61		00:00	00:00	NEW	A15 010	2429,8HK 5919 cyc	2429,8HK 5919 cyc	NEW	V. MULLER 16-10-18
CUSCINETTO ELASTOMERICO	109-0111-04-101	LK3398		00:00	00:00	NEW	A15 010				
CUSCINETTO ELASTOMERICO	109-0111-04-101	LK3397		00:00	00:00	NEW	A15 010				
CUSCINETTO ELASTOMERICO	109-0111-04-101	LK3399		00:00	00:00	NEW	A15 010				
CUSCINETTO ELASTOMERICO	109-0111-04-101	LK3396		00:00	00:00	NEW	A15 010				
DAMPER BRACKET ASSY	109-0111-07-113	R5166		00:00	00:00	NEW	A15 010	1628,9	1628,9	NEW	11-8-16
DAMPER BRACKET ASSY	109-0111-07-113	R5170		00:00	00:00	NEW	A15 010	1323,1	1323,1	NEW	4/16/16
DAMPER BRACKET ASSY	109-0111-07-113	R5171		00:00	00:00	NEW	A15 010	1323,1	1323,1	NEW	4/16/16
DAMPER BRACKET ASSY	109-0111-07-113	R5172		00:00	00:00	NEW	A15 010	1628,9	1628,9	NEW	11-8-16
SLIDING RING ASSY	109-0111-09-101	V288		00:00	00:00	NEW	A15 010	2429,8	2429,8	NEW	10/25/18
FLANGE ASSY SCISSOR BRACKET	109-0111-11-105	Q796		00:00	00:00	NEW	A15 010	2123,6	2123,6	NEW	3/15/18
DROP STOP PLATE	109-0111-17-101	V121		00:00	00:00	NEW	A15 010	2429,8	2429,8	NEW	10/10/18

Rev. 3

AQ 12-04

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Chapter n°65.....
 Part n°

ACTIVITY RECORD			DATE (44)	ORGANIZATION (45)	STAMP AND SIGNATURE (46)
DATE (40)	ASSY TOTAL TIME (41)	TASK (42)			
4/23/24	9118,8	Inspected Main Rotor Assembly IAW AW 119	4/23/24	7SER066B	

Rev. 3

AQ 12-04



LOG CARD

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Sezione 4

Chapter n°65.....
Part n°

MANDATORY DIRECTIVES				DIRECTIVES COMPLIANCE				OPTIONAL DIRECTIVES						
DIRECTIVE NUMBER (47)	ISSUE (48)	DATE OF COMPLIANCE (49)	ORGANIZATION (50)	STAMP SIGNATURE (51)	DIRECTIVE NUMBER (47)	ISSUE (48)	DATE OF COMPLIANCE (49)	ORGANIZATION (50)	STAMP SIGNATURE (51)	DIRECTIVE NUMBER (47)	ISSUE (48)	DATE OF COMPLIANCE (49)	ORGANIZATION (50)	STAMP SIGNATURE (51)

Rev. 3

AQ 12-04



LOG CARD

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Sezione 1

Chapter n°65.....
Part n°

DESCRIPTION (1)	P/N (2)	SN (3)	MANUFACTURER NAME (4)	ASSEMBLY DATE (5)	RETIREMENT LIFE (6)
MAIN ROTOR ASSY	109-0112-02-101	V19	AGUSTA	8/2011	
	P/N (7)	SN (8)	MANUFACTURER NAME (9)	DATE OF CHANGE (10)	RETIREMENT LIFE (11)
	P/N (7)	SN (8)	MANUFACTURER NAME (9)	DATE OF CHANGE (10)	RETIREMENT LIFE (11)

NOTES (12)

ASSEMBLY HISTORICAL RECORD

DATE (13)	AC			ASSY			ORGANIZATION (19)	STAMP AND SIGNATURE (20)	DATE (21)	AC			ASSY			REASON OF REMOVAL (25)	ORGANIZATION (26)	STAMP AND SIGNATURE (27)
	R. MARKS (14)	N/C (15)	TOTAL TIME (16)	TOTAL TIME (17)	TIME SINCE OH (18)	TOTAL TIME (22)				TOTAL TIME (23)	TIME SINCE OH (24)	TOTAL TIME (22)	TOTAL TIME (23)	TIME SINCE OH (24)				
12-23-11	NS11YS	14782	00:00	00:00	New		Agusta		4/25/21	4183	1010.7	4183	1010.7	New	Inspection	7SER066B		

INSTALLATION

REMOVAL

Rev. 3

AQ 12-04



LOG CARD

Section 2

NOTICE THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

ATA Chapter

ASSY P/N (26)		109-0112-02-101		ASSY S/N (27)		V19							
COMPONENT DATA				INSTALLATION				REMOVAL					
DESCRIPTION (28)	P/N (29)	S/N (30)	MANUFACTURING DATE (31)	RETIREMENT LIFE / TIME LIMITS (32)	COMPONENT				COMPONENT				
					ASSY TOTAL HOURS (33)	TOTAL HOURS (34)	TIME SINCE OH (35)	DATE (36)	ASSY TOTAL HOURS (38)	TOTAL HOURS (39)	TOTAL HOURS WITH PENALTY FACTOR (40)	TIME SINCE OH (41)	DATE (42)
					TOTAL LANDINGS (33)	TOTAL LANDINGS (34)	LANDINGS SINCE OH (35)	STAMP AND SIGNATURE (37)	TOTAL LANDINGS (38)	TOTAL LANDINGS (39)	TOTAL LANDINGS WITH PENALTY FACTOR (40)	LANDINGS SINCE OH (41)	STAMP AND SIGNATURE (43)
					TOTAL LIFTS/CYCLES (33)	TOTAL LIFTS/CYCLES (34)	LIFTS/CYCLES SINCE OH (35)		TOTAL LIFTS/CYCLES (38)	TOTAL LIFTS/CYCLES (39)	TOTAL LIFTS/CYCLES WITH PENALTY FACTOR (40)	LIFTS/CYCLES SINCE OH (41)	
DAMPER BRACKET ASSY	109-0111-07-117	V546			3619.6	UNK	NEW						
PITCH CONTROL LEVER	109-0112-04-105	V189			3865.5	3862.5	NEW	5/19/22					
DAMPER Bracket Assy	109-0111-07-117	AW3258			4028.5	0.0	New	10.3.22					
DAMPER Bracket ASSY	109-0111-07-117	AW3254			4028.5	0.0	New	10.3.22					
DAMPER Bracket ASSY	109-0111-07-117	AW3737			4028.5	0.0	New	10.3.22					
Locking Damper Pin	109-0111-30-101	P3441			2429.8	0.0	NEW	9.26.18					



AgustaWestland

LOG CARD

Section 2

Chapter n°
Part n°

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

LIMITED LIFE COMPONENTS INSTALLED ON ASSY

COMPONENT DATA				INSTALLATION				REMOVAL			
DESCRIPTION (28)	P/N (29)	S/N (30)	RETIREMENT LIFE (31)	ASSY TOTAL TIME (32)	COMP. TOTAL TIME (33)	COMP. TIME SINCE OH (34)	STAMP AND SIGNATURE (35)	ASSY TOTAL TIME (36)	COMP. TOTAL TIME (37)	COMP. TIME SINCE OH (38)	STAMP AND SIGNATURE (39)
MAIN ROTOR LAG DAMPER	109-0112-05-107	2230		3441.6	1814.9	0:00					
MAIN ROTOR LAG DAMPER	109-0112-05-107	M010800688		3882.1	4782.3	0:00					
MAIN ROTOR LAG DAMPER	109-0112-05-107	M0R2572		3375.1	12387.4	0:00					
MAIN ROTOR LAG DAMPER	109-0112-05-107	M011201253		2947.5	6821.6	0:00					